

MCPS 9

Multi Channel Process System

Change Control



CAD Computer GmbH & Co. KG

Mackensteiner Str. 19

D - 41751 Viersen

Tel.: +49 (2162) 81615 – 0

E-Mail: Support@CAD-Computer.de

URL: www.MCPS.de

Kurz-Zeichen	Dokument	Prozess	Ablage/Storage	Erstellt/Created	Freigabe/Release	Seite/Page
CHC9	AA15	E	S:\CAD-QMS\MCPS 9\QME\MCPS9_Change_Control.docx	01.10.2026	01.10.2026	1 / 2

QMS: Change Control MCPS 9

Release version 9.0.1.1 (01.09.2026)

Criticality "C" : 0 = Software extension, no error; 1 = Low , ..., 3 = High Side effect "Se": 1 = low,..., 3 = high Comment "Com": BF = BugFix, NF = New Function

Date of release	Version	Description of changes	Date of test / result	C	Se	Com
07.10.2026	9.0.1.6	XDL: Autodetect was possible during data acquisition	07.10.2026 / OK (GR)	3	1	BF
		Automatic gap filling could generate a lot of the error message <S/N mismatch>	07.10.2026 / OK (GR)	2	1	BF

Kurz-Zeichen	Dokument	Prozess	Ablage/Storage	Erstellt/Created	Freigabe/Release	Seite/Page
CHC9	AA15	E	S:\CAD-QMS\MCPS 9\QME\MCPS9_Change_Control.docx	01.10.2026	01.10.2026	2 / 2